




Accelerometer Connection Details



Cable From Accelerometer

Rev No	DRF No	Date Drg	Drg By	Appd By	Material: N/A	 Hansford Sensors <i>Excellence in Vibration Monitoring</i> Hansford Sensors Ltd Artisan, Hillbottom Road Sands Industrial Estate High Wycombe Bucks HP12 4HJ		 Do Not Scale All Dimensions in mm Unless Otherwise Stated	Description: HS-BE Connection enclosure connection details Drawing No: CD018	Scale: 1 : 1 Sheet: 1 of 1	Form Number: QF024 Issue 2
A	Release	16.11.10	MAB	MJS	Tolerances Unless Stated 0 or 0.0 ±0.5 0.00 ±0.15 Angle ±5°	1/6 Finish All Over Threads g6 H6					

1	2	3	4	5	6	7	8
---	---	---	---	---	---	---	---